




```

1  #include "SPI.h"
2  #include "LCD.h"
3  #include "LCD2.h"
4  #include "ADC.h"
5  #include "External_EEPROM.h"
6  uint16 temp,temp2,y,x,flag=0;
7  int main(void)
8  {
9      DDRE=0xff;
10     DDRK=0;
11     DDRH=0xff;
12     PORTH=0;
13     SPI_Slave_init();
14     LCD_Init();
15     LCD2_Init();
16     ADC_init();
17     LCD2_DisplayStringRowCol(0,0,"Temp in :    C");
18     LCD2_DisplayStringRowCol(1,0,"Temp out :    C");
19
20     while (1)
21     {
22
23
24         PORTK=0xff;
25
26
27

```



Code



Protues



开发资料



软件教程



注意事项



LICENSE.txt



README.MD



仿真.png



配套资料说明.txt