




```

1 /
2 // 发射引脚（接PNP三极管b极）
3 // PNP三极管e极接20电阻，c极接红外发射管
4
5 #include <REG51.h>
6 #include <intrins.h>
7 #define uchar unsigned char
8 #define uint unsigned int
9
10 #define SBM 0x80 //识别码
11
12 #define m9 (65536-9000) //约9mS
13 #define m4_5 (65536-4500) //约4.5mS
14 #define m1_6 (65536-1630) //约1.65mS
15 #define m_65 (65536-580) //约0.65mS
16 #define m_56 (65536-560) //约0.56mS
17 #define m40 (65536-40000) //约40mS
18 #define m56 (65536-56000) //56mS
19 #define m2_25 (65536-2250) //约2.25mS
20
21 sbit IR = P3^6; //定义发射引脚（接PNP三极管基极）
22 sbit LED = P3^7; //发射指示灯
23
24 uchar KEY(void);
25 void SanZhuan(void);
26 void ZZ(uchar x);
27 void Z0(uchar temp);
28 void TT0(bit BT,uint x);
29 void YS(uchar time);

```



程序（核心文件）



仿真（核心文件）



开发资料



软件教程



注意事项



仿真.png



红外线遥控器NEC编码.pdf



论文降重秘籍.pdf



配套资料源码.txt