




```
1  /*头文件*/
2  #include<reg52.h>
3  #include <intrins.h>
4  #define uint unsigned int
5  #define uchar unsigned char
6  #define yh 0x80 //LCD第一行的初始位置
7  #define er 0x80+0x40 //LCD第二行初始位置
8  sbit set_key=P1^3;    //"设置"键 K1
9  sbit add_key=P1^4;    //"加"键 K2
10 sbit cut_key=P1^5;    //"减"键 K3
11
12 sbit rs=P1^0;
13 sbit en=P1^1;
14 sbit speak=P3^5;    // 蜂鸣器
15 sbit led=P3^4;    // led
16 sbit DCF=P3^6;    //电磁阀
17 sbit FS=P3^7;    //fengshan
18
19 sbit CS=P2^0;
20 sbit CLK=P2^2;
21 sbit D0=P2^3;
22 sbit DI=P2^4; //数据输入
23 sbit DQ1=P1^2;
24 uint DD1;
25 uchar flog4,temp,a,flog1;
26 uchar code tab1[]={"AC:  --  --  "}; //测量值显示的固定字符
27 uchar code tab2[]={"St:  --  --  "}; //报警值显示的固定字符
28 uchar T_data[2]={0,0};
29 uint set_Y=5;    //报警初始值的设定
30 uint set_C=6;    //报警初始值的设定
31 uint set_T=60;    //报警初始值的设定
```



protues 仿真文件



开发资料



软件教程



源程序



注意事项



仿真截图.png



配套资料说明.txt